

Document Title	Number	Rev	Date	Type
TIMKEN Replacement Parts for Certain Pratt & Whitney Canada PT6A and PT6T Engine Models	T-800	B	2/12/16	ILR
3013102E/E3013102, 3030102E/E3030102 Power Turbine Blade Inspection, Repair Limits and Overhaul Criteria	T-801	C	2/12/16	ILR
E3123131-02, E3123071-01 Blade, CT	T-802	C	2/12/16	ILR
PT6A Oil System Monitoring for Reduction Gear Bearings Set No. E3035020 (P/N E3101985-03), Set No. E3035029 (P/N E3101985-05), Set No. E3035030 (P/N E3101985-02), Set No. E3035031 (P/N E3101985-01)	T-803	A	2/12/16	SB
PT6A Increased Monitoring of Chip Detector, E3024765	T-804	B	2/12/16	Alert SB
PT6A Increased Monitoring of Engine Chip Detectors, E3028456, E3037304, E3101455-02, E3101525-02	T-807	IR	2/12/16	Alert SB
PT6A Instructions for Removal of Sun Gear P/N's E3028456, E3037304 and Planet Gear P/N's E3101455-02, E3101525-02	T-808	IR	2/12/16	Alert SB
E3045741-01 Blade, Turbine Compressor	T-809	IR	2/12/16	ILR
To Be Determined	T-810	IR	TBD	ILR
Compressor Turbine Blade Inspection (E3045741-01)	T-811	A	2/12/16	SB