

Document Title	Number	Rev	Date	Type
EXTEx Instructions for Continued Airworthiness	T-700	C	10/23/15	ICA
EXTEx Inspection Limits and Repair: TAI-6040-036-101 (Bearing, Ball, Annular)	T-701	A	2/12/16	ILR
EXTEx Service Bulletin (AMOC to AD 90-26-11): TAI-4011-179-003 (Cleviss), ASI-4011-180-003 (Fitting, Grip, Drag Brace Assembly)	T-704	IR	11/03/15	SB
EXTEx Instructions for Continued Airworthiness: TAI-4011-105-001, TAI-4011-105-103	T-705	A	7/11/18	ICA
EXTEx Airworthiness Limitation Schedule	T-710	G	6/05/18	SB
Service Information Letter – Operating in Severely Corrosive Environment (ASI-4011-151-1)	T-711	A	5/30/17	SIL
EXTEx Instructions for Continued Airworthiness: 2E6-310-004-101, 2E6-310-004-103	T-712	A	5/28/21	ICA
EXTEx Instructions for Continued Airworthiness: 2E6-011-132-113, 2E6-011-132-113A	T-713	A	12/04/19	ICA
EXTEx Instructions for Continued Airworthiness: 2E6-011-150-105	T-714	IR	8/24/20	ICA
EXTEx Service Bulletin: TAI-6040-032-105 (Bearing, Ball Duplex)	T-716	IR	6/24/20	SB